

Division of Oil, Gas, & Mining
Mining Report

07/14/92

MINE ID: S011001

MINE NAME: LAMB, SESSIONS & YOUNG QUARRY

OPERATOR: LAMB, SESSIONS & YOUNG

CONTACT: JON R YOUNG

ADDRESS: 2402 BROADVIEW COURT
SANDY UT 84092

PHONE: (801)571-6558

Surface Owner: COUNTY

BLM #:

Mineral Owner: FEE

Lease #:

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Range	Town
		SE				29	1.0E	5.0N

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: S

Mine Status (PRO,ACT,SUS,RET): SUS

Acreage: 4

Minerals Mined
STONE

DATE
RECEIVED

TENTATIVE APPROVAL
DATE

FINAL APPROVAL
DATE

LAST INSPECTED

09/28/90

/ /

10/01/90

07/08/92

BOND TYPE: N/A

BOND AMOUNT:

ANNUAL REPORT YEAR: 91

NONCOMPLIANCE NOTICES: 0	DATE ISSUED: / /	DATE RESOLVED: / /
VIOLATIONS: 0	DATE ISSUED: / /	DATE RESOLVED: / /
REVISIONS: 0	DATE REC'D: / /	DATE APPROVED: / /
AMENDMENTS: 0	DATE REC'D: / /	DATE APPROVED: / /

COMMENTS:

THIS MINING OPERATION IN DAVIS COUNTY LIES ALONG THE RAILROAD. THE OPERATORS HAVE A FILE NO 248 UT 0046-01 WITH (STATE LANDS)? 1990 ANNUAL REPORT STATED THEY WERE APPLYING FOR A VARIANCE WITH DAVIS COUNTY TO WORK THE QUARRY. 1991 REPORTS THAT USFS GAVE PERMISSION TO USE A SERVICE ROAD TO PROPERTY. OPERATOR APPLYING FOR A ZONING CHANGE W/DAVIS CO. SITE EXAMINED ON FOOT AS BOULDERS BLOCKED THE OLD ROAD. SITE IS BELIEVED TO BE IN BEND OF OLD HIGHWAY & ON SOUTH BELIEVED TO BE IN BEND OF OLD HIGHWAY & ON SOUTH BANK OF WEBER RIVER. NO MININ